Work Orde Wednesday, July												Page
Item ID: Revision ID: Item Name:	D4034-043 Fwd Upper Rib	b Assembly		Accept					Setup	Start		
	7/14/2010	Start Qty: 3.00 Req'd Qty: 3.00	4 1881ES (111 LE)		Cust Item 1 Customer:	ID:				Stop.		.
Approvals:	Process Plan	n:	Date:/0-7-	Tooling: SPC (Y/N):		ate:		Neg.	Run	Start Stop		
Sequence ID/ Work Center ID Draw Nbr	<u> </u>	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty	1	eject umbe	Insp.
D4034	A Revis	sion Nbr						 		. 11	·	r Stamp
Large Fab		Memo 1- Assemb	S. rod Batch: MOJO ole ribs to hoop and weld as ushing in rib as per dwg	0.00 0.00 per dwg DT9564				- Ef	Pl,	0 10 · 8	7	- 21
10 	(QC9- Inspect visual per	r QSI004- Fusion Welds	0.00								
QC Quality Control		Memo		0.00				(D)	D 10.0	2J. 3	۲	: 1
20 QC Quality Control	•	QC5- Inspect part comp Memo	leteness to step on W/O	0.00	rslev			B				

W/O:	İ		W	ORK ORDER CHANG	iES				
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		· · · · · · · · · · · · · · · · · · ·						}	
Part No):	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQA		Date: _	
	Res	solution:	Dispositi	on:	_ QA: N/C C	losed:	ļ	Date: _	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (NC	₹)			
DATE	STEP	Description of NC			ion B	Verifica			Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		C	Chief Eng	QC Inspector
	1								
	1 1							ŀ	

Work Orde Wednesday, July												Page 2
Revision ID: Item Name:	D4034-043 Fwd Upper Ri 7/14/2010 7/22/2010	ib Assembly Start Qty: 3.00 Req'd Qty: 3.00		Accept	Cust Item 1 Customer:				Setup	Start Stop		
Approvals:		n:		Tooling: SPC (Y/N):		ate:		1	Run	Start Stop	. 151	88 18 18 18 18 18 18 18
Sequence ID/ Work Center ID 130 Packaging Packaging		Operation Description Identify as per dwg & Sto Memo	ck Location: WA	Set Up/ Run Hours 0.00 SAO 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Rejo Qty	l .	Reject lumber	Insp.
40 CC Cuality Control		QC21- Final Inspection - V	Work Order Release	0.00						6	0/0	1/23 /

WORK ORDER CHANCES									
W/O:				WORK ORDER (CHANGES	•			1
DATE	STEP		PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				**					
· · · · · · · · · · · · · · · · · · ·)							
Part No) :		PAR #:	Fault Category:	NCR: Yes	s No DQ	A:	Date: _	
	F	Resolution:		Disposition:	QA: N/C	Closed:		Date: _	
				WORK OPPED NON CON	CODMANCE (NO	'D'			

NCR:			WORK ORDE	ER NON-CONFORMANO	CE (NCR)		•	
		Description of NC		Corrective Action Section B		Verification	on Approval	Approvai
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
	;							:
· - ·								
					*			

Picklist Print Wednesday, July 14, 2010 8:19:29 AM Work Order ID: 60545 Parent Item: D4034-043

Start Date: 7/14/2010

Required Date: 7/22/2010

Page 1

Start Qty: 3.00

Required Oty: 3.00

Parent Item Name: Fwd Upper Rib Assembly

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

IPP Rev:B as

per dwg revA 10.03.15 verified by:EC

P		3.15 verified by:E	EC			·.D u.s							
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on	Qty per Kit	Total	Qty	Date	C4-4
D4034-1		Manufactured	No					Hand		Qty		Issued	Status
Rib						100	Each	6.0000		3	1		
				Location		Loc Q	<u>Oty</u>	Loc Code			Cfr.	10.	07.2
D4034-5	1.00	Manufactured	No	WA	59837	100	6			3)			-
	 					100	Each	3.0000	1	2			:

Rib

Manufactured

Location	Loc	<u>Oty</u>	Loc Code
WA		3	
59845		3	
	100	Each	16.0000

Location Loc Qty Loc Code WA 16 58406 58974 59980 14

Spacer Bushing

D2327-3

W/O:			W	ORK ORDER CHANG	iES					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	,	Date	Cty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						Ì				
						_		ļ		
Part No	•	PAR #:	Fault Cat	egory:	NCR: Y	es N	o DQA :		Date:	
Resolution:			Dispositi	on:	QA: N/0	Clos	sed:		Date: _	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC			ion B		Verifica	ion	Chief Eng / Prod Mgr Date: Date:	Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Section C			QC Inspector
										:

Picklist Print

Wednesday, July 14, 2010 8:19:29 AM

Page 2

Work Order ID: 60545

Parent Item:

D4034-043

Parent Item Name: Fwd Upper Rib Assembly

Manufactured



Start Date: 7/14/2010

Start Qty: 3.00

Required Date: 7/22/2010 Required Qty: 3.00

D4021-7

Ноор

<u>Location</u>	Loc Oty	<u>L</u>
WA	7	
58039	1	
58702	1	
59839	5	


100

Each


Loc Code

7.0000


W/O:			W	ORK ORDER CHAN	IGES					t
DATE	STEP	PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									Frod Wigh	,
					•					
Part No		PAR #:							Date:	
	R	esolution:							Date: _	
NCR:			WORK ORI	DER NON-CONFORI	MANCE	E (NCR)			
DATE	STEP	Description of NC			ection B		Verific	ition		Approval
DAIL	012.	Section A	Initial Chief Eng	Action Description Chief Eng			Sectio	h C		QC Inspector
<u>.</u>										
·-·										
				·						
										1



W/O:			'							
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	,	Date	Qty	Approval Chief Eng /	Approval QC Inspector
	:							<u> </u>	Prod Mgr	
	,									
Part No	:	PAR #:	Fault Cat	tegory:	NCR: Y	es N	o DQA		Date: _	
	R	esolution:	Dispositi	ion:	_ QA: N/0	C Clos	sed:	ļ	Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (N	CR)				
DATE	OTED	Description of NC		Corrective Action Section			Verifica	tion	Approval	Approval
DATE	STEP	Section A	of NC verification		Chief Eng	QC Inspector				
									1	
									1	
					[]					
								5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		




W/O:		WORK ORDER CHANGES									•	
DATE	STEP	PRO	CEDURE CH	EDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No:		PAR #:	Fault Category: NCR: Ye			R: Yes I	es No DQA:		: Date:			
Resolution:			Disposit	Disposition:			QA: N/C Closed:			Date:		
NCR:		V	VORK OR	DER NON	I-CONFORM	MANCE	(NCR)					
DATE	STEP	Description of NC				ection B	Verifica			Approval		
	0.2.	Section A	Initial Chief Eng	ACT	on Description Chief Eng	1	Sign & Date	Section	С	Chief Eng	QC Inspector	
·												
				*.								
						!						
1	i	•									ì	



Dart Aerospace L	.td
------------------	-----

W/O:		WORK ORDER CHANGES								
DATE STEP		PROCEDURE CHANGE			Ву	Date		Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					1					
										
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Y	es N	o DQA:		_ Date: _	
Reso		esolution:	Disposition:			QA: N/C Closed:				
NCR:			WORK ORE	DER NON-CONFORMA	ANCE (N	CR)	11.			
DATE	STEP	Description of NC			tion B Verifica		tion Approval	Approval	Approval	
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sig	jn & ate	Section C		Chief Eng	QC Inspector
_										
						•				



Dart Aerospac	e:	Ltd
---------------	----	-----

W/O:		WORK ORDER CHANGES							· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PRO	PROCEDURE CHANGE				Date		Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•						i		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	es N	o DQA:		Date:	
	R	esolution:	Dispositio	n:	QA: N/C Closed:			Date:		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	CR)				
DATE	STEP Description of Section A	Description of NC	Corrective Action Section B			Verifica		tion Approval	Approval	
DATE		Section A	Initial Chief Eng	Action Description Chief Eng		n & ite	Section C		Chief Eng	QC Inspector
									i	
					-					
		·		•						